	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
1	BRS	L1	64	440/88F.ccls.	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	
2	BRS	L2	16	L1 and heat	US- PGPUB ; USPAT ; USOCR ; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	
3	BRS	<b>L</b> 3	50	440/88HE.ccls.	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
4	BRS	L4	3	L3 and fuel	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	
5	BRS	<b>L</b> 5	15	440/88D.ccls.	US- PGPUB ; USPAT ;	2005/01/1 1 13:41	
6	BRS	L6	15	440/88D.ccls.	US- PGPUB ; USPAT ;	2005/01/1 1 13:41	

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
7	BRS	<b>L</b> 7	9	L5 and fuel	US- PGPUB ; USPAT ; USOCR ; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	
8	BRS	L8 ·	132	440/88C.ccls.	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:41	
9	BRS	L9	46	L8 and fuel	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:42	

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
10	BRS	L10	163	123/541.ccls.	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:42	
11	BRS	L11	44	L10 and electric	US- PGPUB ; USPAT ;	2005/01/1 1 13:42	
12	BRS	L12	41	Lll and cooling	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:42	

·	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
13	BRS	L13	8	L10 and thermoelectric	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB	2005/01/1 1 13:42	
14	BRS	L14	12019	marine and fuel	US- PGPUB ; USPAT ;	2005/01/1 1 13:42	
15	BRS	L15	4001	L14 and cooling	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:43	

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
16	BRS	L16	25	L14 and Peltier	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB	2005/01/1 1 13:43	